


4-4-05



Pictures:

- (A) Pooling of Water Between 1302 Key DR and 1300 Key DR.
- (B) Water backing up under driveway of 1300 Key DR.
- (C) Water Rushing through culvert (44" deep) in front of 1300 Key DR.

From storm that occurred on 3/24/05.



Ⓐ, Water beginning to pool
in side yard between
← 1302 Key Drive and 1300 Key Dr →



Ⓐ² Water continued to rise in side
side between

← 1302 Key and 1300 Key Dr →



① Water backing up above opening
of storm drain pipe running
under the driveway of 1300 Key drive



Ⓟ₂ Ponding of water → continuing
to rise



1300 Key DR
DRIVEWAY

← (C) Water Rushing through →
culvert in front of 1300 Key DR.
Culvert when dry is 44" high,
water depth at the time of this
picture is at least 42" deep.